

State of California — The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 2D

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource name(s) or number (assigned by recorder) 471-473 Oak St.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted *a. County: San Francisco

and (P2b and P2c or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad: San Francisco North, Calif. Date: 1956 (rev. 1973)

*c. Address: 471-473 Oak St. City: San Francisco Zip: 94102

d. UTM: Zone: 10 mE/ _____ mN (G.P.S.)

e. Other Locational Data: Assessor's Parcel Number (Map, Block, Lot): 0840-039

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries.)

471-473 Oak St. is located on a 26' x 64' lot on the south side of Oak Street, between Laguna and Buchanan Streets. Built circa 1895, 471-473 Oak St is a three-story, wood frame, multiple family building designed in the Stick/Eastlake style. The rectangular-plan building, clad in drop wood siding is capped by a gable roof. The primary façade faces north and is two bays wide. The façade has corner quoins at both ends of the elevation. The basement story features a garage in the left bay with paneled surround and a straight flight of terrazzo steps in the right bay leading to the main entrances on the second story. The main entrances are set within paneled recesses with paneled surrounds and a continuous bracketed door hood. The entrances have modern, paneled wood doors and arched transoms. The left bay contains a semi-hexagonal bay window with paneled spandrels; double-hung, arched wood sash windows; and paneled surrounds with flat, scroll-sawn brackets. The window ends in an intermediary cornice with pediment over the central window. The third story has a similar bay window in the left bay with a plain cornice line. The right bay of the third story has a single double-hung, arched wood window with pilaster surround and bracketed pediment hood. The elevation terminates in a paneled frieze and a bracketed modillion cornice. A small arched pediment is set above the center of the left bay. The building appears to be in good condition.

*P3b. Resource Attributes: (list attributes and codes) HP3. Multiple family property

*P4. Resources Present: Building Structure Object Site District Element of District Other



*P5b. Photo: (view and date)

View from north
10/27/2006

*P6. Date Constructed/Age and

Sources: Historic
1900; rev. ca. 1895
SF Assessor; Sanborn Maps

*P7. Owner and Address:

Erick K Kleinbub
2988 Pacific Ave #6
San Francisco, CA

*P8. Recorded by:

Page & Turnbull, Inc.; KS, TS
724 Pine Street
San Francisco, CA 94108

*P9. Date Recorded:

10/27/2006

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none") None

*Attachments: None Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (list)